

Topic: Pick Code Changes

Date: 07/28/09

Internal To: Sales, Customer Service, Management

External To: All Distributors and OEMs

From: Joseph Engram, Product Manager

In August 2009, Itron's Liquid Measurement Division will be changing to the Oracle database management system. This change will be mostly invisible to Itron's customers through 2009. The one change that will be most evident will be the Sales Order Acknowledgements (SOA) and the Pick Codes you will see.

The first change will affect configured products within configured products. The E4000, NexGen, and Datamate 2200 are all configured into another product.

The E4000 is configured within RP150, RP200, RL125, RL150, RL200, RML2000, and MP200-S. You will continue to pick a "4" for your register when setting up the meter. The difference is when you receive your SOA.

EXAMPLES:

- RL200-118SPG42 sent in on Purchase Order
- RL200-118SPGBO2 received on SOA

The "BO" is tied to the specific E4000 configuration the customer requires. Keep in mind that this will all be handled internally. You will not have to add the "BO" yourself but you will need to spec out your E4000 configuration.

The NexGens and Datamates will also be configured similarly within Mass Flow meters.

EXAMPLES:

- M012-88010102DS or M012-88010102NS sent in on Purchase Order
- M012-88010102DBS or M012-88010102NFS received on SOA

Again, the DB and NF are both tied to the specific Datamate and NexGen the customer requires.

****Attached is an Excel Spreadsheet defining each new pick code with its respective configuration. New configurations and codes will be added as needed.****

Next, the configured Refined Fuel meters Pick Codes will also change regarding the registers. We have covered the E4000's above within the Refined Fuels meters, but this also pertains to the mechanical registers. If a pick code was normally "A", it will now be "0A" on the SOA. If it was "2", it will now be "02" and so on. If the pick code is lower case such as f, it will now be "VF" or "a" it will now be "VA" on the SOA being that this is a Veeder Root register.

****Exception: The lower case pick code of "t" will change to "TT." The Pick code "T" will follow the previously stated format and will be "OT".****

EXAMPLES:

- RL100-108A12S sent in on Purchase Order
- RL100-108A102S received on SOA
- RL100-108A1aS sent in on Purchase Order
- RL100-108A1VAS received on SOA

E4000**New Pick Code**

E4000-SES50S000BB	AA
E4000-SIS40S000MU	AD
E4000-SIS40S00MMU	AG
E4000-SIHFASA0LUU	AJ
E4000-SISS0SADSUU	AK
E4000-SISFASASACC	AN
E4000-SIHFASABAUU	AO
E4000-SIHFBSA22UU	AP
E4000-SIHS0SADLUU	AQ
E4000-SEHS0SA0SMU	AS
E4000-SIS4ASA0ASE	AT
E4000-SISFASACAUU	AV
E4000-SIHFAS02AUU	AW
E4000-SISDRSA00UU	AZ
E4000-SIHFRS0SLUU	BD
E4000-SIHFRS00LUU	BI
E4000-SISFASABAUU	BM
E4000-SISFBSABSUU	BO
E4000-SIHFRSAS0UU	BQ
E4000-SIHFRSA00UU	BP
E4000-SISFRSAC0CU	BR
E4000-SESFrsa00UU	BT
E4000-SEHFRSA00UU	BU
E4000-SEHFRSAS0UU	BX
E4000-SESFOSAS0UU	BV
E4000-SIHS0SADSUU	BW

Datamate 2200

DM2200-1000000	DA
DM2200-1000001	DB
DM2200-1011000	DC
DM2200-1200000	DD
DM2200-1200001	DE

NexGen

SFT100-0001000	NA
SFT100-0200100	NB
SFT100-1000000	NC
SFT100-1000100	ND
SFT100-1001000	NE
SFT100-1200000	NF
SFT100-1201100	NH
SFT100-2200000	NI
SFT100-2200100	NJ